



Photo 1. Aerial View of Powerhouse Intake Channel and Powerhouse



Photo 2. Powerhouse and Bank Erosion from Downstream



Photo 3. Channel Erosion adjacent to Powerhouse Intake



Photo 4. Repairs at Mouth of Powerhouse Intake Channel



Photo 5. Erosion at Upriver Dam from Downstream



Photo 6. Repairs South of Dam Face from Upstream